

# ENGINEERING CHANGE NOTICE

## DART AEROSPACE LTD

MPP

Date: 09.09.03	Job No.: 00269	ADR Yes/No: N	ADR Date:	ECN #: 09- 658
Product No.: D130-787		Created By: KB	Approved By: <del>KB</del>	
Product Name: TAS Installation		Checked By: <del>KB</del>	General Manager Approval: NA	

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	
Production Engineering Coord	Y	DD/EC	
Production Document Control	Y	BG	
Customer Technical Support	N		

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	N		
QC Coordinator	N		
Marketing	Y	SW	
Customer Order Processing	N		

**Reason for Change:** Add quantity 2 of P/N 190113 BNC right angle connector to D130-787-013 Kit.  
Quantity of P/N 190109 TNC right angle connector incorrect. Quantity of P/N 190109 TNC right angle connectors in D130-787-013 Kit should be 10 instead of 4.

**Documents Affected:**  
DSI 9479 REV. A  
MDL-D130-787 REV. C

PARTS MUST COMPLY

☒

PREVIOUS PARTS SATISFACTORY

☐

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3		N			

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	Y	SW		
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09.09.09 <del>KB</del>
10	Update Controlled PDF Files	Y	KJ		09.09.09 <del>KB</del>
11	Update Master Document List (MDL)	Y	KB	MDL-D130-787 REV. C	09.09.09 <del>KB</del>
12	Update Document Record (DR)	Y	KJ	Rev. L	09.09.09 <del>KB</del>
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	N			
16	Update / Verify ARC Database	N			
17	Create / Update Change Record Form	N			
18	Create / Update PPP's	N			
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ		09.09.09 <del>KB</del>
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.09.09 <del>KB</del>
22					
23					

**Description / Action:**  
RECOMMEND PUTTING 2x D130-787-013 KITS IN STOCK  
UPDATE ROUTING/ESTIMATE/BOM FOR D130-787-013 TO MATCH DSI 9479.  
ENSURE ALL D130-787-013 GOING INTO STOCK INCLUDE EXTRA CONNECTORS PER DSI 9479  
ENSURE EXTRA CONNECTORS ARE SHIPPED TO PAPILLON / BLACKMOUNTAIN AVIONICS ASAP

w/o 52164

Done w

ECN Verified & Complete: \_\_\_\_\_ Date: \_\_\_\_\_